## Northeast Reliability Interconnect

Bangor Hydro-Electric Company



U.S.G.S. data: Monroe Lake Quadrangle, 1990



Balloons on the left.



Balloons in the middle.



Balloons on the right.

# Existing Conditions 9A Panoramic view looking north from the northern end of First Machias Lake. Three sets of weather balloons are visible above the treeline. Balloon locations were established for reference purposes only and do not represent final structure locations. Photographs by TJD&A, October 1, 2004.

# Northeast Reliability Interconnect

Bangor Hydro-Electric Company





U.S.G.S. data: Monroe Lake Quadrangle, 1990

## Photosimulation 9B

Photosimulation of the proposed project looking north. The upper portion of two structures will be visible from the northern end of First Machias Lake. Photographs by TJD&A, October 1, 2004.